



Remark:

1. Blind caps are 2XM50X1.5 and 2XM20X1.5

|  |      |   |          |                                   |                      |              |    |
|--|------|---|----------|-----------------------------------|----------------------|--------------|----|
| <b>HOYER</b><br>EXCEEDING EXPECTATIONS |      | Hoyer Motors<br>Over Hadstenvvej 42, DK-8370 Hadsten<br>Tel: +45 86982111<br>Fax: +45 86981779<br>www.hoyermotors.com |          | DEBUR AND<br>BREAK SHARP<br>EDGES | DO NOT SCALE DRAWING | REVISION     | 01 |
| DRAWN                                  | NAME | SIGNATURE   | DATE     |                                   | TITLE:               |              |    |
| CHK'D                                  | TH   |   | 20201229 |                                   | HMC4-200L-B5         |              |    |
| APP'VD                                 |      |   |          |                                   |                      |              |    |
| MFG                                    |      |   |          |                                   |                      |              |    |
| Q.A                                    |      |   |          | MATERIAL:                         | DWG NO.              | A3           |    |
|  |      |   |          | cast iron                         | 4HMC200002W          |              |    |
|  |      |   |          | WEIGHT: kg                        | SCALE:1:10           | SHEET 1 OF 1 |    |